REPORT OF CHANNEL CONDITIONS							Page 1 of 1		
(FOR CHANNELS 400 FEET WIDE OR GREATER) (ER 1130-2-316)							March 2002		
TO: Executive Director, Ports Authority Commonwealth of Puerto Rico, San Juan, Puerto Rico				FROM USACE. District Engineer Attn: CESAJ-CO-OM Jacksonville. Florida					
RIVER/HARBOR NAME AND STATE Arecibo Harbor, Puerto Rico				MINIMUM DEPTHS IN EACH 1/4 WIDTH OF CHANNEL ENTERING FROM SEAWARD					
NAME OF CHANNEL	Date	AUTHORI	ZED PROJ	ED PROJECT		Left	Right	Right	
	of Survey	Width	Length	Depth	Outside Quarter (feet)	Inside Quarter (feet)	Inside Quarter (feet)	Outside Quarter (feet)	
		(feet)	(miles)	(feet)	(Icci)	(ICCL)	(Icci)	(1661)	
Entrance Channel: From 150 feet east of Red Buoy-2 to 200 feet east of Green Buoy-1.	Mar-2002	650	0.1	25	29.0	26.5	26.0	26.5	
Deep Water Terminal Basin: from 200 feet east of Green Buoy-1 to terminus of Inner Basin.	Mar-2002	400-650	0.3	25	9.1 (1)	8.1 (1)	18.2 (1)	12.8 (1)	

Remarks:

⁽¹⁾ Shoaling located throughout middle half of channel in vicinity of Red Buoy-6 and extending along the southern edge of channel. Shoaling also located in the northern corner of Basin.